REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	4/23/2018	Time:	10:36 AM
Name of School Corporation:		PERU	J COMMUNIT	Y SCHOOLS		Corp ID:	525635
Address of School Corporation:			35 W 3rd St				
City:	Peru		Zip:	46970		County Number:	52
VIN:	4UZABRDJ79CAD329	6		License Number:	32093	Bus Number:	3
Make of Body:	Thomas Built Buses, Inc.	Year:	2008	Make of Chassis:	Freightliner	Year:	2009
Bus Type:	С			Mileage:	146850		
Inspection Status:	R		Inspected Bv:	Randy McPike		PE:	7018

Violations - Rejected

	<u>Description</u> <u>Description</u>
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
46-1-2	Any seat back or bottom is loose
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.