REPORT OF SCHOOL BUS INSPECTION

Type of 11:48 Annual Date: 4/26/2018 **Time**: Inspection: AM Name of School Corporation: EAST PORTER COUNTY SCHOOL CORP Corp ID: 646510 **Address of School Corporation:** PO Box 370 County City: Kouts Zip: 46347 64 Number: License VIN: 4UZABRDJXACAN9738 32012 **Bus Number:** 22 Number: Make of Thomas Built Buses, Year: 2009 Freightliner Year: Make of Body: 2010 Inc. Chassis: **Bus Type:** С Mileage: 89597 Inspection Inspected R PE: 7558 Tim Grayson Status: By:

Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

52-1-3 Rubber bushings are missing, damaged or deteriorated

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.