

REPORT OF SCHOOL BUS INSPECTION

| | | |
|---|------------------------------------|--|
| Type of Inspection: Re-Inspection | Date: 5/1/2018 | Time: 8:24 AM |
| Name of School Corporation: CRAWFORD CO. COMM. SCHOOL CORP | Corp ID: 131300 | |
| Address of School Corporation: 5808 E Administration Rd | | |
| City: Marengo | Zip: 47140 | County Number: 13 |
| VIN: 4RDBUSKPXEB405437 | License Number: 55NEW | Bus Number: 55 |
| Make of Body: IC Corporation | Year: 2014 | Make of Chassis: IC Corporation |
| Year: 2014 | Mileage: 85933 | Year: 2014 |
| Bus Type: C | | |
| Inspection Status: O | Inspected By: Kelly Hammond | PE: 6682 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 32-1-5 | See Notes: Any defect inspector deems a violation not listed |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.