REPORT OF SCHOOL BUS INSPECTION

| Type of Inspection: | Re-Inspection | | | Date: | 5/1/2018 | Time: | 8:45 AM |
|--------------------------------|----------------------------|--------------------------------|------------------|---------------------|-----------|-------------------|------------|
| Name of School Corporation: | | CRAWFORD CO. COMM. SCHOOL CORP | | | Corp ID: | 131300 | |
| Address of School Corporation: | | 5808 E Administration Rd | | | | | |
| City: | Marengo | | Zip: | 47140 | | County Number: | 13 |
| VIN: | 1GBJG31K091163308 | | | License Number: | 81641 | Bus Number: | 85 |
| Make of Body: | Collins Bus Corporation | Year: | 2009 | Make of Chassis: | Chevrolet | Year: | 2009 |
| Bus Type: | A1 | | | Mileage: | 89569 | | |
| Inspection Status | : A | | Inspected By: | Kelly Hammond | | PE: | 6682 |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.

2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.