REPORT OF SCHOOL BUS INSPECTION

Type of 9:01 Time: Annual Date: 5/1/2018 Inspection: AM Name of School Corporation: TRI-TOWNSHIP SCH CORP Corp ID: 464915 **Address of School Corporation:** 309 School Drive County City: Wanatah Zip: 46390 46 Number: License VIN: 4UZABRDT1ECFF6292 Ff6292 **Bus Number:** 1214 Number: Make of Thomas Built Buses, Year: 2013 Freightliner Year: Make of Body: 2012 Inc. Chassis: **Bus Type:** С Mileage: 77056 Inspected PE: **Inspection Status:** R Tim Grayson 7558 By:

Violations - Rejected

Inspection Code

52-1-3 Rubber bushings are missing, damaged or deteriorated

Description

52-1-2 Any shock absorber is leaking fluid

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.