## REPORT OF SCHOOL BUS INSPECTION

Type of 8:42 Annual Date: 5/1/2018 Time: Inspection: AM EASTERN HOWARD COMM, SCH. CORP 343480 Name of School Corporation: Corp ID: **Address of School Corporation:** 221 W Main St County City: Greentown Zip: 46936 34 Number: License VIN: 1T7YT4E25A1126655 33091 Bus Number: 3 Number: Thomas Built Buses, Year: 2009 Thomas Built Buses, Year: Make of Make of Body: 2010 Chassis: Inc. Bus Type: D Mileage: 78728 Inspection Inspected PE: R Randy McPike 7018 Status: By:

## Violations - Rejected

<u>Inspection</u>	Description
Code	<u>Description</u>

The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

35-1-1 A heater motor is not operating properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.