# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:

Annual Date: 5/3/2018 Time: 8:49
AM

Name of School Corporation: OAK HILL UNITED SCHOOL CORP. Corp ID: 525625

Address of School Corporation: PO Box 550

City: Converse Zip: 46919 County Number: 52

VIN: 4UZABRDT8ECFF6290 License Number: 8

Make of Body: Thomas Built Buses, Inc. Year: 2013 Make of Chassis: Freightliner Year: 2014

Bus Type: C Mileage: 47852

Inspection Status: O Inspected By: Randy McPike PE: 7018

### **Violations - Rejected**

### <u>Inspection Code</u> <u>Description</u>

35-1-1 A heater motor is not operating properly

52-1-1 There are any loose, broken, or missing mountings

# **Violations - Out of Service**

Inspection Code	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

# **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.