

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/3/2018	Time:	8:49 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4UZABRDT8ECFF6290		License Number:	1122	Bus Number:	8	
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Freightliner	Year:	2014
Bus Type:	C			Mileage:	47852		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
52-1-1	There are any loose, broken, or missing mountings

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.