

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/3/2018	Time:	9:59 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRDT1CCBA1231	License Number:	1127	Bus Number:	15
Make of Body:	Thomas Built Buses, Inc.	Year:	2011	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	72923	Year:	2012
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly
35-1-1	A heater motor is not operating properly
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.