

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	5/1/2018	Time:	11:24 AM
Name of School Corporation:	VIGO COUNTY SCHOOL CORPORATION			Corp ID:	848030
Address of School Corporation:	3250 Maple Ave				
City:	Terre Haute	Zip:	47804	County Number:	84
VIN:	4DRBWAAR0GB111829	License Number:	10028	Bus Number:	1551
Make of Body:	IC Corporation	Year:	2015	Make of Chassis:	IC Corporation
Bus Type:	D	Mileage:	39652	Year:	2016
Inspection Status:	O	Inspected By:	Byron Goodman	PE:	7008

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-9	Tailpipe has been reduced in a size (diameter) from the rear of the muffler
2-1-3	Any back-up light lens is cracked, broken, faded or missing
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
31-2-1	Frame is deteriorated, cracked, broken or severely bent

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.