

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	5/4/2018	Time:	2:21 PM
Name of School Corporation:	MACONAQUAH SCHOOL CORPORATION	Corp ID:	525615		
Address of School Corporation:	7932 S Strawtown Pike				
City:	Bunker Hill	Zip:	46914	County Number:	52
VIN:	1T7YT4E21B1133667	License Number:	74482	Bus Number:	1
Make of Body:	Thomas Built Buses, Inc.	Year:	2010	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	D	Mileage:	82173		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
67-1-2	Rims are bent or loose
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
53-1-2	Any leaf spring extends more than 1/4 inch beyond the vertical alignment of the spring stack

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat
53-2-5	“U” bolts are loose, broken, or missing

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver’s seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.

