## **REPORT OF SCHOOL BUS INSPECTION**

Type of Inspection: Annual			Date:	5/7/2018	Time:	9:13 AM
Name of School Corporation:		OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School	Corporation:	PO Box 550				
City:	Converse	Zip:	46919		County Number:	52
VIN:	4DRBUSKN29B095	305	License Number:	30876	Bus Number:	7
Make of Body:	IC Corporation Year	: 2008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	С		Mileage:	127020		
Inspection Status:	0	Inspected By:	Randy McPike		PE:	7018

## **Violations - Rejected**

Inspection <u>Code</u>	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
20-1-8	If bus manufactured after 5-2-1994, positive door opening device is missing or fails to operate properly

## **Violations - Out of Service**

Inspection Code Description

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.