REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	5/7/2018	Time:	10:17 AM
Name of School Corporation:		OAK	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:		PO Box 550					
City:	Converse		Zip:	46919		County Number:	52
VIN:	4UZABRDT5ACAP448	36		License Number:	72344	Bus Number:	17
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Freightliner	Year:	2010
Bus Type:	С			Mileage:	172509		
Inspection Status:	R		Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly
52-1-1	There are any loose, broken, or missing mountings

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.