REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	5/7/2018	Time:	10:31 AM
Name of School Corporation:		OAK	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:			PO Box 550				
City:	Converse		Zip:	46919		County Number:	52
VIN:	1GB3GSBG5G113712	1		License Number:	39152	Bus Number:	1SAV
Make of Body:	Thomas Built Buses, Inc.	Year:	: 2016	Make of Chassis:	Chevrolet	Year:	2016
Bus Type:	A2			Mileage:	10917		
Inspection Status	:: R		Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection <u>Code</u>	Description
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
68-1-1	Washers do not function properly in any manner

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.