

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/7/2018	Time:	11:42 AM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	1GBJG31K491156782	License Number:	76952	Bus Number:	3SAV
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	80380	Year:	2009
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
50-1-2	The seat belt cutter is not secured
35-1-1	A heater motor is not operating properly
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.