

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	5/7/2018	Time:	11:42 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	1GBJG31K491156782		License Number:	76952	Bus Number:	3SAV	
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Chevrolet	Year:	2009
Bus Type:	A2		Mileage:	80380			
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
68-1-1	Washers do not function properly in any manner
50-1-2	The seat belt cutter is not secured
35-1-1	A heater motor is not operating properly
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

### Violations - Out of Service

### Inspection Code Description

### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.