REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/11/2018	**Time:**	8:54 AM
Name of School Corporation:	TAYLOR COMMUNITY SCHOOL CORP.			**Corp ID:**	343460
Address of School Corporation:	3750 E CR 300 S				
City:	Kokomo	**Zip:**	46902	**County Number:**	34
VIN:	1GB3GRBG3G1189324	**License Number:**	39000	**Bus Number:**	22
Make of Body:	Starcraft **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2016
Bus Type:	A2	**Mileage:**	9607		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
2-1-1	Required back-up lights do not function.
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4” min), 2 40”x40”x56” triangular bandages, 6 3”x3” gauze pads, 4 2”x4.1 yard rolls of gauze, 3 oval eye pads, 1 1”x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**