

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 5/11/2018 **Time:** 9:05 AM
Name of School Corporation: TAYLOR COMMUNITY SCHOOL CORP. **Corp ID:** 343460
Address of School Corporation: 3750 E CR 300 S
City: Kokomo **Zip:** 46902 **County Number:** 34
VIN: 1GB3GRBG6G1187387 **License Number:** 39004 **Bus Number:** 12
Make of Body: Starcraft **Year:** 2015 **Make of Chassis:** Chevrolet **Year:** 2016
Bus Type: A2 **Mileage:** 9082
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-4 | The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**