

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 5/11/2018 **Time:** 9:15 AM  
**Name of School Corporation:** TAYLOR COMMUNITY SCHOOL CORP. **Corp ID:** 343460  
**Address of School Corporation:** 3750 E CR 300 S  
**City:** Kokomo **Zip:** 46902 **County Number:** 34  
**VIN:** 1GB6G5BG0E1109691 **License Number:** 21769 **Bus Number:** 16  
**Make of Body:** Thomas Built Buses, Inc. **Year:** 2013 **Make of Chassis:** Chevrolet **Year:** 2014  
**Bus Type:** A2 **Mileage:** 20820  
**Inspection Status:** O **Inspected By:** Randy McPike **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
79-1-3	If equipped the emergency warning buzzer does not sound

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
20-2-1	Is no audible signal when the emergency door is open and ignition switch is on

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**