## REPORT OF SCHOOL BUS INSPECTION

Type of 9:17 Re-Inspection Date: 5/11/2018 **Time**: Inspection: AM Name of School Corporation: TAYLOR COMMUNITY SCHOOL CORP. 343460 Corp ID: **Address of School Corporation:** 3750 E CR 300 S County City: Kokomo Zip: 46902 34 Number: License VIN: 1GB6G5BG0E1109691 21769 **Bus Number:** 16 Number: Make of Thomas Built Buses, Chevrolet Year: Year: 2013 Make of Body: 2014 Inc. Chassis: **Bus Type:** A2 Mileage: 20820 Inspected **Inspection Status:** R Randy McPike PE: 7018 By:

## Violations - Rejected

Inspection Code Description

The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

**Violations - Out of Service** 

<u>Inspection Code</u> <u>Description</u>

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.