REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		Date:	5/11/2018	Time:	9:46 AM
Name of Schoo Address of Sch	I Corporation: TAN ool Corporation:	LOR COMMU 3750 E CR	INITY SCHOOL (300 S	CORP.	Corp ID:	343460
City:	Kokomo	Zip:	46902		County Number:	34
VIN:	4UZABRDT2ACAN8262		License Number:	32972	Bus Number:	15
Make of Body:	Thomas Built Buses, Yea Inc.	ır: 2009	Make of Chassis:	Thomas Built Buses, Inc.	Year:	2010
Bus Type:	С		Mileage:	177069		
Inspection Status:	R	Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection <u>Code</u>	Description
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
79-1-3	If equipped the emergency warning buzzer does not sound
2-1-4	LED type lights have 25% or more of the pixels inoperable in any one light

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.