REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual			Date:	5/11/2018	Time:	10:31 AM
Name of School Co	orporation:	KOKO	MO SCHOOL	CORPORATION		Corp ID:	343500
Address of School Corporation:			620 W Deffenb	augh			
City:	Kokomo		Zip:	46901		County Number:	34
VIN:	4DRBUSKN1D)B3065	49	License Number:	4769	Bus Number:	228
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2013
Bus Type:	С			Mileage:	63846		
Inspection Status:	R		Inspected By:	Randy McPike		PE:	7018

Violations - Rejected

Inspection
CodeDescription8The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2
40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3
oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.