

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/11/2018	<b>Time:</b>	10:08 AM		
<b>Name of School Corporation:</b>	ELWOOD COMMUNITY SCHOOL CORP.			<b>Corp ID:</b>	485280		
<b>Address of School Corporation:</b>	1306 N Anderson St						
<b>City:</b>	Elwood	<b>Zip:</b>	46036	<b>County Number:</b>	48		
<b>VIN:</b>	4DRBUSKP59B673964	<b>License Number:</b>	32109	<b>Bus Number:</b>	2		
<b>Make of Body:</b>	IC Corporation	<b>Year:</b>	2009	<b>Make of Chassis:</b>	IC Corporation	<b>Year:</b>	2009
<b>Bus Type:</b>	B	<b>Mileage:</b>	113643				
<b>Inspection Status:</b>	A	<b>Inspected By:</b>	Jeremy Mason	<b>PE:</b>	8139		

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**