

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 5/14/2018	<b>Time:</b> 10:56 AM
<b>Name of School Corporation:</b>	NORTH MIAMI COMMUNITY SCHOOLS	<b>Corp ID:</b> 525620
<b>Address of School Corporation:</b>	PO Box 218	
<b>City:</b> Denver	<b>Zip:</b> 46926	<b>County Number:</b> 52
<b>VIN:</b> 1GBJG31U171151196	<b>License Number:</b> 32354	<b>Bus Number:</b> A3
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2007	<b>Make of Chassis:</b> Chevrolet
<b>Year:</b> 2007	<b>Mileage:</b> 104287	<b>PE:</b> 7018
<b>Bus Type:</b> A2		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Randy McPike	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
14-2-2	Any crossmember is rusted sufficiently to weaken floor supports

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**