

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|-------------------------------|------------------------|-----------------|-------------------------|----------|
| Type of Inspection: | Annual | Date: | 5/14/2018 | Time: | 11:46 AM |
| Name of School Corporation: | NORTH MIAMI COMMUNITY SCHOOLS | | Corp ID: | 525620 | |
| Address of School Corporation: | PO Box 218 | | | | |
| City: | Denver | Zip: | 46926 | County Number: | 52 |
| VIN: | 1GB6G3AG9A1152779 | License Number: | 84300 | Bus Number: | A4 |
| Make of Body: | Thomas Built Buses, Inc. | Year: | 2009 | Make of Chassis: | GMC |
| Year: | 2010 | Mileage: | 136053 | Year: | 2010 |
| Bus Type: | A2 | Inspected By: | Randy McPike | PE: | 7018 |
| Inspection Status: | R | | | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-4 | The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction. |
| 41-1-5 | There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.) |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.