REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/15/2018	**Time:**	9:19 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	**Zip:**	45242	**County Number:**	18
VIN:	4DRBUC8P9JB524149	**License Number:**	B483N	**Bus Number:**	M4
Make of Body:	IC Corporation **Year:** 2019	**Make of Chassis:**	IC Corporation	**Year:**	2018
Bus Type:	C	**Mileage:**	16917		
Inspection Status:	R	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
52-1-2	Any shock absorber is leaking fluid
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
26-1-2	Not fully charged

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.