

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 5/15/2018      **Time:** 9:35 AM  
**Name of School Corporation:** AUXILIO SERVICES (MUNCIE)      **Corp ID:** 251807  
**Address of School Corporation:** 11260 Cornell Park Dr Suite 700  
**City:** Cincinnati      **Zip:** 45242      **County Number:** 18  
**VIN:** 1GB3GRBF7H1116451      **License Number:** B889N      **Bus Number:** M41  
**Make of Body:** Chevrolet      **Year:** 2016      **Make of Chassis:** Chevrolet      **Year:** 2017  
**Bus Type:** A1      **Mileage:** 12795  
**Inspection Status:** R      **Inspected By:** Jamie Hotchkiss      **PE:** 6458

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

### Violations - Out of Service

Inspection Code      Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**