## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:5/16/2018Time:9:05 AMName of School Corporation:NORTH SPENCER COUNTY SCHOOL COCorp ID:747385

**Address of School Corporation:** 3720 E SR 162

City:Lincoln CityZip:47552County Number:74VIN:4DRBUAAN98A493207License Number:Bus Number:11Make of Body:IC Corporation Year:2007Make of Chassis:IC Corporation Year:2008

Bus Type: C Mileage: 97724

Inspection Status: R Inspected By: Kelly Hammond PE: 6682

## Violations - Rejected

Inspection Code	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
65-1-1	Any lens is cracked, broken or discolored
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).
20-1-2	Excessive effort is needed to open the emergency door

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.