

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|-----------------|-------------------------|-----------|
| Type of Inspection: | Annual | Date: | 5/18/2018 | Time: | 9:06 AM |
| Name of School Corporation: | MUNCIE COMMUNITY SCHOOLS | Corp ID: | 181970 | | |
| Address of School Corporation: | 2501 N Oakwood | | | | |
| City: | Muncie | Zip: | 47304 | County Number: | 18 |
| VIN: | 1GB6G2AG6A1148487 | License Number: | 83029 | Bus Number: | 6 |
| Make of Body: | Collins Bus Corporation | Year: | 2010 | Make of Chassis: | Chevrolet |
| Bus Type: | | Mileage: | 19745 | | |
| Inspection Status: | <input type="radio"/> | Inspected By: | Jamie Hotchkiss | PE: | 6458 |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|---|
| 23-1-3 | Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted). |

Violations - Out of Service

Inspection Code Description

Bus Type Description