REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	**Date:**	5/22/2018	**Time:**	11:01 AM
Name of School Corporation:	SCHOOL CITY OF MISHAWAKA			**Corp ID:**	717200
Address of School Corporation:	1402 S Main St				
City:	Mishawaka	**Zip:**	46544	**County Number:**	71
VIN:	1HA3GRBG4HN001783	**License Number:**	51785	**Bus Number:**	5
Make of Body:	Starcraft **Year:** 2017	**Make of Chassis:**	Star Trans	**Year:**	2017
Bus Type:	A2	**Mileage:**	2000		
Inspection Status:	O	**Inspected By:**	Travis Harrold	**PE:**	8022

Violations - Rejected

Inspection Code	Description
64-1-1	Turn signals are not properly mounted
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

Violations - Out of Service

Inspection Code	Description
63-2-3	Any tire is flat
8-2-1	There is no brake certification, or the certification has expired or is not signed
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**