

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 5/22/2018      **Time:** 11:01 AM  
**Name of School Corporation:** SCHOOL CITY OF MISHAWAKA      **Corp ID:** 717200  
**Address of School Corporation:** 1402 S Main St  
**City:** Mishawaka      **Zip:** 46544      **County Number:** 71  
**VIN:** 1HA3GRBG4HN001783      **License Number:** 51785      **Bus Number:** 5  
**Make of Body:** Starcraft      **Year:** 2017      **Make of Chassis:** Star Trans      **Year:** 2017  
**Bus Type:** A2      **Mileage:** 2000  
**Inspection Status:** O      **Inspected By:** Travis Harrold      **PE:** 8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-1	Turn signals are not properly mounted
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
8-2-1	There is no brake certification, or the certification has expired or is not signed
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**