

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/5/2018	Time:	11:05 AM
Name of School Corporation:	JOHN GLENN SCHOOL CORPORATION			Corp ID:	717150
Address of School Corporation:	101 John Glen Dr				
City:	Walkerton	Zip:	46574	County Number:	71
VIN:	1GDHG31F9Y1236117	License Number:	83978	Bus Number:	32
Make of Body:	GMC	Year:	2000	Make of Chassis:	GMC
Bus Type:	A1	Mileage:	86465	Year:	2000
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
50-1-2	The seat belt cutter is not secured
24-1-5	Any paint is badly faded or peeling

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)(Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.