REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 6/5/2018 **Time**: 11:05 AM Name of School Corporation: JOHN GLENN SCHOOL CORPORATION Corp ID: 717150 Address of School Corporation: 101 John Glen Dr City: Walkerton Zip: 46574 County Number: 71 VIN: 1GDHG31F9Y1236117 **Bus Number:** License Number: 83978 32 Make of Body: GMC Year: 2000 Make of Chassis: GMC Year: 2000 **Bus Type:** Α1 Mileage: 86465 **Inspected By:** Travis Harrold PE: 8022 **Inspection Status:** 0

Violations - Rejected

Inspection Code	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
50-1-2	The seat belt cutter is not secured
24-1-5	Any paint is badly faded or peeling

Violations - Out of Service

<u>Inspection</u> <u>Code</u>	<u>Description</u>
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.