

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/6/2018	<b>Time:</b>	12:17 PM
<b>Name of School Corporation:</b>	JOHN GLENN SCHOOL CORPORATION			<b>Corp ID:</b>	717150
<b>Address of School Corporation:</b>	101 John Glen Dr				
<b>City:</b>	Walkerton	<b>Zip:</b>	46574	<b>County Number:</b>	71
<b>VIN:</b>	4UZ6CJAA7XCA36161	<b>License Number:</b>	72446	<b>Bus Number:</b>	34
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	1999	<b>Make of Chassis:</b>	Freightliner
<b>Year:</b>		<b>Year:</b>		<b>Year:</b>	1999
<b>Bus Type:</b>		<b>Mileage:</b>	128779		
<b>Inspection Status:</b>	<input type="radio"/>	<b>Inspected By:</b>	Travis Harrold	<b>PE:</b>	8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	Any interior protrusions have sharp edges or corners
24-1-1	The bus body has rust or rusted through areas which may weaken the body
29-1-3	There are holes in the floor
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
46-1-2	Any seat back or bottom is loose
30-1-1	There are any holes in the floor
30-1-2	There are weak areas due to deterioration

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
30-2-1	Floor sags or buckles substantially when stood upon. (NOTE: Check under bus to verify deterioration.)

### Bus Type Description