

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/6/2018	Time:	12:17 PM
Name of School Corporation:	JOHN GLENN SCHOOL CORPORATION	Corp ID:	717150		
Address of School Corporation:	101 John Glen Dr				
City:	Walkerton	Zip:	46574	County Number:	71
VIN:	4UZ6CJAA7XCA36161	License Number:	72446	Bus Number:	34
Make of Body:	Blue Bird Corporation	Year:	1999	Make of Chassis:	Freightliner
Bus Type:		Mileage:	128779	Year:	1999
Inspection Status:	O	Inspected By:	Travis Harrold	PE:	8022

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
41-1-2	Any interior protrusions have sharp edges or corners
24-1-1	The bus body has rust or rusted through areas which may weaken the body
29-1-3	There are holes in the floor
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
46-1-2	Any seat back or bottom is loose
30-1-1	There are any holes in the floor
30-1-2	There are weak areas due to deterioration

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
30-2-1	Floor sags or buckles substantially when stood upon. (NOTE: Check under bus to verify deterioration.)

Bus Type Description