## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: AnnualDate:6/7/2018Time:9:53 AMName of School Corporation:UNION SCHOOL CORPORATIONCorp ID:686795

Address of School Corporation: 8707 W US 36

City:ModocZip:47358County Number:68VIN:4DRBUSKP5BB256298License Number:8227Bus Number:6Make of Body:IC Corporation Year:2009

Bus Type: C Mileage: 90478

Inspection Status: O Inspected By: Jamie Hotchkiss PE: 6458

**Violations - Rejected** 

**Inspection Code Description** 

**Violations - Out of Service** 

<u>Inspection Code</u> <u>Description</u>

32-2-1 There is fuel leaking from any point on in the fuel system

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.