

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/12/2018	Time:	2:52 PM
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.	Corp ID:	525625		
Address of School Corporation:	PO Box 550				
City:	Converse	Zip:	46919	County Number:	52
VIN:	4UZABRDT0BCAU0750	License Number:	10675	Bus Number:	19
Make of Body:	Thomas Built Buses, Inc.	Year:	2009	Make of Chassis:	Freightliner
Bus Type:	C	Mileage:	85774		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.