

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/12/2018	Time:	3:13 PM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4DRBUSKN49B095306		License Number:	30875	Bus Number:	16	
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation	Year:	2009
Bus Type:	C			Mileage:	135938		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-3	Any required padding is missing

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.