## REPORT OF SCHOOL BUS INSPECTION

Type of 11:49 6/13/2018 **Time**: Annual Date: Inspection: AM Name of School Corporation: CULVER COMMUNITY SCHOOLS CORP. 505455 Corp ID: **Address of School Corporation:** PO Box 231 County City: Culver Zip: 46511 50 Number: License VIN: 1GB3G2BG5C1107773 9208 **Bus Number:** 25 Number: Make of Collins Bus Year: 2011 GMC 2012 Make of Body: Year: Corporation Chassis: **Bus Type:** Α1 Mileage: 73603 Inspected PE: **Inspection Status:** O Travis Harrold 8022 By:

Violations - Rejected

**Inspection Code Description** 

**Violations - Out of Service** 

<u>Inspection Code</u> <u>Description</u>

50-2-1 There is no seat belt cutter in the vehicle

## **Bus Type Description**

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.