REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/15/2018	**Time:**	10:40 AM
Name of School Corporation:	NORTHERN RUSH COUNTY SCHOOLS INC			**Corp ID:**	9955
Address of School Corporation:	929 E South Street				
City:	MAYS	**Zip:**	46155	**County Number:**	70
VIN:	4DRBRAAN13A947251	**License Number:**	B389L	**Bus Number:**	7
Make of Body:	IC Corporation **Year:** 2002	**Make of Chassis:**	IC Corporation	**Year:**	2002
Bus Type:	C	**Mileage:**	160106		
Inspection Status:	R	**Inspected By:**	Jeremy Mason	**PE:**	8139

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4” min), 2 40”x40”x56” triangular bandages, 6 3”x3” gauze pads, 4 2”x4.1 yard rolls of gauze, 3 oval eye pads, 1 1”x5 yard of adhesive tape, 1 label instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.