

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/21/2018	Time:	8:21 AM		
Name of School Corporation:	AVON COMMUNITY SCHOOLS			Corp ID:	323315		
Address of School Corporation:	7203 E HWY 36						
City:	Avon	Zip:	46123	County Number:	32		
VIN:	4DRBWAAR87A421135		License Number:	30164	Bus Number:	130	
Make of Body:	IC Corporation	Year:	2006	Make of Chassis:	IC Corporation	Year:	2007
Bus Type:	D			Mileage:	93139		
Inspection Status:	O	Inspected By:	Alex Willis	PE:	4760		

## Violations - Rejected

### Inspection Code Description

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.