

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	6/22/2018	<b>Time:</b>	9:54 AM
<b>Name of School Corporation:</b>	NORTHWESTERN SCHOOL CORP.			<b>Corp ID:</b>	343470
<b>Address of School Corporation:</b>	3075 N Washington St				
<b>City:</b>	Kokomo	<b>Zip:</b>	46901	<b>County Number:</b>	34
<b>VIN:</b>	1BAKFCPA2CF287487	<b>License Number:</b>	B692F	<b>Bus Number:</b>	11
<b>Make of Body:</b>	Blue Bird Corporation	<b>Year:</b>	2011	<b>Make of Chassis:</b>	Blue Bird Corporation
<b>Bus Type:</b>	C	<b>Mileage:</b>	90736	<b>Year:</b>	2011
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
24-1-5	Any paint is badly faded or peeling
22-1-1	A dripping oil or fluid leak
57-1-5	Step-well light is missing or inoperative
28-1-4	The first aid kit is not complete: 3 packs of 16 1x3 adhesive strips, 1 scissor (4" min), 2 40"x40"x56" triangular bandages, 6 3"x3" gauze pads, 4 2"x4.1 yard rolls of gauze, 3 oval eye pads, 1 1"x5 yard of adhesive tape, 1 label instruction.
46-1-3	Any required padding is missing

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**