## REPORT OF SCHOOL BUS INSPECTION

Type of Annual Date: 6/25/2018 Time: 11:03 AM

Name of School Corporation: BLACKFORD COUNTY SCHOOLS Corp ID: 50515

Address of School Corporation: 668 W CR 200S

City:Hartford CityZip:47348County Number:5VIN:4DRBUC8N1HB511520License Number:13617Bus Number:316Make of Body:IC Corporation Year:2017

Bus Type: C Mileage: 15433

Inspection Status: R Inspected By: Jamie Hotchkiss PE: 6458

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

35-1-1 A heater motor is not operating properly

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.