REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	6/27/2018	**Time:**	7:57 AM
Name of School Corporation:	BLACKFORD COUNTY SCHOOLS			**Corp ID:**	50515
Address of School Corporation:	668 W CR 200S				
City:	Hartford City	**Zip:**	47348	**County Number:**	5
VIN:	4DRBUAAN6BB327325	**License Number:**	74622	**Bus Number:**	110
Make of Body:	IC Corporation **Year:** 2010	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	85198		
Inspection Status:	R	**Inspected By:**	Jamie Hotchkiss	**PE:**	6458

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.