## REPORT OF SCHOOL BUS INSPECTION

| Type of<br>Inspection: | Re-Inspection     |                          | Date:               | 6/28/2018                   | Time:             | 10:36<br>AM |
|------------------------|-------------------|--------------------------|---------------------|-----------------------------|-------------------|-------------|
| Name of School C       | •                 | TH PUTNAM<br>3999 S US 2 |                     | HOOLS                       | Corp ID:          | 676705      |
| City:                  | Greencastle       | Zip:                     | 46135               |                             | County<br>Number: | 67          |
| VIN:                   | 4UZABRDJ0BCA      | AW0737                   | License<br>Number:  | 74705                       | Bus Number:       | 1004        |
| Make of Body:          | Freightliner Year | : 2010                   | Make of<br>Chassis: | Thomas Built Buses,<br>Inc. | Year:             | 2010        |
| Bus Type:              | С                 |                          | Mileage:            | 82895                       |                   |             |
| Inspection<br>Status:  | 0                 | Inspected<br>By:         | Byron Goodman       |                             | PE:               | 7008        |

## **Violations - Rejected**

| Inspection Code | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|

26-1-2 Not fully charged

74-1-1 The anti-vandalism device fails to operate

## **Violations - Out of Service**

| Inspection<br>Code | <u>Description</u>  |  |  |  |  |
|--------------------|---|--|--|--|--|
| 7-2-4              | Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at |  |  |  |  |
|                    | other than a proper connection).  |  |  |  |  |

## **Bus Type Description**

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.