REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/28/2018	**Time:**	9:24 AM
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			**Corp ID:**	80750
Address of School Corporation:	2 S 3rd St.				
City:	Flora **Zip:**	46929		**County Number:**	8
VIN:	4DRBUAAP3BB334279	**License Number:**	75017	**Bus Number:**	20
Make of Body:	IC Corporation **Year:** 2011	**Make of Chassis:**	IC Corporation	**Year:**	2011
Bus Type:	C	**Mileage:**	79577		
Inspection Status:	R **Inspected By:**	Nate King		**PE:**	7421

Violations - Rejected

Inspection Code	Description
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.