

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/28/2018	Time:	10:30 AM		
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750		
Address of School Corporation:	2 S 3rd St.						
City:	Flora	Zip:	46929	County Number:	8		
VIN:	4DRBUSKN8EB765918		License Number:	6222	Bus Number:	18	
Make of Body:	IC Corporation	Year:	2014	Make of Chassis:	IC Corporation	Year:	2014
Bus Type:	D		Mileage:	64013			
Inspection Status:	R	Inspected By:	Nate King	PE:	7421		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
23-1-2	Any component has deteriorated and allows the escape of exhaust gases (with the engine idling and the system unrestricted)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.