

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 6/28/2018	Time: 10:47 AM
Name of School Corporation: CARROLL CONS. SCHOOL CORP.	Corp ID: 80750	
Address of School Corporation: 2 S 3rd St.		
City: Flora	Zip: 46929	County Number: 8
VIN: 1BAKF29F261574	License Number: 30559	Bus Number: 11
Make of Body: Blue Bird Corporation	Year: 2009	Make of Chassis: Blue Bird Corporation
Year: 2009		Year: 2009
Bus Type: C	Mileage: 126057	
Inspection Status: O	Inspected By: Nate King	PE: 7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
32-2-1	There is fuel leaking from any point on in the fuel system

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.