

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	6/28/2018	Time:	10:55 AM
Name of School Corporation:	CARROLL CONS. SCHOOL CORP.			Corp ID:	80750
Address of School Corporation:	2 S 3rd St.				
City:	Flora	Zip:	46929	County Number:	8
VIN:	4DRBUAAP78B498840	License Number:	31624	Bus Number:	23
Make of Body:	IC Corporation	Year:	2008	Make of Chassis:	IC Corporation
Year:		Year:		Year:	2008
Bus Type:	C	Mileage:	132548		
Inspection Status:	R	Inspected By:	Nate King	PE:	7421

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
2-1-1	Required back-up lights do not function.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
17-1-1	Any dome light is inoperative

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.