## REPORT OF SCHOOL BUS INSPECTION

Type of 12:19 Time: Re-Inspection Date: 7/9/2018 Inspection: PMName of School Corporation: M.S.D. STEUBEN COUNTY 767615 Corp ID: **Address of School Corporation:** 400 S Martha St County City: Angola Zip: 46703 76 Number: License VIN: 1T7YT4E28D1160786 4424 Bus Number: 30 Number: Thomas Built Buses, Year: 2013 Thomas Built Buses, Year: Make of Make of Body: 2012 Chassis: Inc. **Bus Type:** D Mileage: 48396 Inspection Inspected R PE: 7006 Eric Egbert Status: By:

## Violations - Rejected

<u>Inspection Code</u> <u>Description</u>

One (1) taillight or one (1) brake light does not function

**Violations - Out of Service** 

**Inspection Code Description** 

## **Bus Type Description**

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.